

Planned Outage

Name of the Licensee: *INDIA POWER CORPORATION LIMITED*
 From Date : 22-05-2023

To Date : 28-05-2023

Sl. No.	Feeder / Transformer Name & Number	Time of outage	Time of Restoration	Duration in minutes	Affected area connected to respective feeder /substation	Input load in kW at the time of outage	Input load in kW at the time of restoration	Interruption Reference Number	No. of Objection received from Consumers	Reply given to the objections	Estimated Energy loss in MU
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)	(j)	(k)	(l)
1	Raniganj Square Feeder	22-05-2023 10:38	22-05-2023 13:03	145	All consumers under Raniganj Square Feeder Feeder	0	0	PLRAN202305220107			0.0000
2	Indian Oxygen No. 1 (11 KV)	27-05-2023 10:09	27-05-2023 11:58	109	All consumers under Indian Oxygen No. 1 (11 KV) Feeder	653	131	PLIND202305270049			0.0007
3	KLS	27-05-2023 11:21	27-05-2023 12:39	78	All consumers under KLS Feeder	985	985	PLKLS202305270067			0.0013
4	East Ring -1 (11 KV)	27-05-2023 11:27	27-05-2023 11:57	30	All consumers under East Ring -1 (11 KV) Feeder	653	131	PLEAS202305270016			0.0002
5	Indian Oxygen No. 1 (11 KV)	27-05-2023 13:33	27-05-2023 13:56	23	All consumers under Indian Oxygen No. 1 (11 KV) Feeder	747	187	PLIND202305270050			0.0002
6	Searsol Pumping	27-05-2023 15:47	27-05-2023 17:39	112	All consumers under Searsol Pumping Feeder	625	625	PLSEA202305270012			0.0012
7	Carolina (11 KV)	28-05-2023 16:55	28-05-2023 17:42	47	All consumers under Carolina (11 KV) Feeder	934	187	PLCAR202305280025			0.0004
8	DCM (11 KV)	28-05-2023 18:14	28-05-2023 18:37	23	All consumers under DCM (11 KV) Feeder	467	93	PLDCM202305280018			0.0001
9	Seetalpur-3 (11 KV)	28-05-2023 18:44	28-05-2023 19:10	26	All consumers under Seetalpur-3 (11 KV) Feeder	1494	187	PLSEE202305280015			0.0004

Un-Planned Outage

Name of the Licensee: *INDIA POWER CORPORATION LIMITED*
 From Date : 22-05-2023

To Date : 28-05-2023

Sl. No.	Feeder / Transformer Name & Number	Time of outage	Time of Restoration	Duration in minutes	Affected area connected to respective feeder /substation	Input load in kW at the time of outage	Input load in kW at the time of restoration	Interruption Reference Number	No. of Objection received from Consumers	Reply given to the objections	Estimated Energy loss in MU
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)	(j)	(k)	(l)
1	Ikrah- Dhasal R/M 1	22-05-2023 14:55	22-05-2023 18:17	202	All consumers under Ikrah- Dhasal R/M 1 Feeder	19685	19685	UPIKR202305220021			0.0663
2	Ikrah- Dhasal R/M 2	22-05-2023 14:55	22-05-2023 18:17	202	All consumers under Ikrah- Dhasal R/M 2 Feeder	19685	19685	UPIKR202305220013			0.0663
3	NorthBrook	23-05-2023 16:11	23-05-2023 18:53	162	All consumers under NorthBrook Feeder	156	156	UPNOR202305230028			0.0004
4	Haripur 2	23-05-2023 16:27	23-05-2023 20:40	253	All consumers under Haripur 2 Feeder	0	0	UPHAR202305230011			0.0000
5	Kenda 1	23-05-2023 16:49	23-05-2023 19:14	145	All consumers under Kenda 1 Feeder	785	785	UPKEN202305230016			0.0019
6	Chandmari (11KV)	25-05-2023 16:45	26-05-2023 04:44	719	All consumers under Chandmari (11KV) Feeder	1307	373	UPCHA202305250026			0.0101
7	Central Satgram	25-05-2023 17:55	25-05-2023 19:28	93	All consumers under Central Satgram Feeder	1356	1356	UPCEN202305250028			0.0021
8	Raniganj Section 1	25-05-2023 18:17	26-05-2023 00:56	399	All consumers under Raniganj Section 1 Feeder	1035	1035	UPRAN202305250042			0.0069
9	Raniganj Section 2	25-05-2023 18:17	25-05-2023 22:02	225	All consumers under Raniganj Section 2 Feeder	985	985	UPRAN202305250025			0.0037
10	Sitaldas ji	25-05-2023 18:17	26-05-2023 00:00	343	All consumers under Sitaldas ji Feeder	9670	9670	UPSIT202305250041			0.0553
11	KLS	25-05-2023 18:20	26-05-2023 00:35	375	All consumers under KLS Feeder	985	985	UPKLS202305250066			0.0062
12	Srijan Cement	25-05-2023 18:31	25-05-2023 21:13	162	All consumers under Srijan Cement Feeder	4652	4652	UPSRI202305250053			0.0126
13	Kunustoria tie	25-05-2023 19:10	25-05-2023 22:18	188	All consumers under Kunustoria tie Feeder	986	986	UPKUN202305250032			0.0031
14	Topsi rail	28-05-2023 15:10	28-05-2023 16:56	106	All consumers under Topsi rail Feeder	485	485	UPTOP202305280036			0.0009